



SWAN HOSE
DIVISION

AMERACE CORPORATION, 8929 COLUMBUS PIKE, P.O. BOX 509,
WORTHINGTON, OHIO 43085, (614) 548-6511

US EPA RECORDS CENTER REGION 5



511673

OFFICE OF THE PRESIDENT

June 9, 1981

USEPA - Region V
Sites Notification
Chicago, Illinois 60604

Dear Sir:

Re: Stetzer Road Landfill

A completed EPA Form 8900-1, Notification of Hazardous Waste Sites, is enclosed.

The form identifies a site at which industrial wastes have been disposed at some time in the past. We submit the enclosed form, because some of these wastes may be classified as "hazardous" under the Federal Hazardous Waste Management Program. Under certain conditions, small amounts which exceed EP toxicity thresholds have been observed in a small area on an intermittent basis. Because of the small quantities and the circumstances, it is not believed that any releases pose a significant environmental threat.

Any such "hazardous wastes" were disposed of in connection with much larger quantities of solid waste which EPA has not identified as hazardous, and the notification form should be read in that perspective. For example, in Section "F", we identified the entire parcel of land as the "Total Facility Area". We have not been able to estimate confidently the amount and area of hazardous wastes from reasonably available records and the depth of inquiry contemplated by the Act.

Sincerely,

SWAN HOSE DIVISION
Amerace Corporation

Richard E. Warnick
President

REW:jis
Enc.

JUN 11 1981




**SWAN HOSE
DIVISION**

AMERACE CORPORATION, 8929 COLUMBUS PIKE,
P.O. BOX 509, WORTHINGTON, OHIO 43085

OFFICE OF THE PRESIDENT

USEPA - Region V
Sites Notification
Chicago, Illinois 60604



EPA Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

OH #228 81 06 11

OHS-000-001-366

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Amerace Corporation, Swan Hose Division
Street 8929 North High Street
City Worthington State Ohio Zip Code 43085

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Stetzer Road Site
Street Stetzer Road
Twp. Liberty County Crawford State Ohio Zip Code 44820

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) John Keeney, Division Engineer
Phone (419) 548-6511

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1967 To (Year) 1971

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:
Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

- 1. ☐ Organics
- 2. ☐ Inorganics
- 3. ☒ Solvents
- 4. ☐ Pesticides
- 5. ☒ Heavy metals
- 6. ☐ Acids
- 7. ☐ Bases
- 8. ☐ PCBs
- 9. ☐ Mixed Municipal Waste
- 10. ☐ Unknown
- 11. ☐ Other (Specify)

Source of Waste:
Place an X in the appropriate boxes.

- 1. ☐ Mining
- 2. ☐ Construction
- 3. ☐ Textiles
- 4. ☐ Fertilizer
- 5. ☐ Paper/Printing
- 6. ☐ Leather Tanning
- 7. ☐ Iron/Steel Foundry
- 8. ☐ Chemical, General
- 9. ☐ Plating/Polishing
- 10. ☐ Military/Ammunition
- 11. ☐ Electrical Conductors
- 12. ☐ Transformers
- 13. ☐ Utility Companies
- 14. ☐ Sanitary/Refuse
- 15. ☐ Photofinish
- 16. ☐ Lab Hospital
- 17. ☐ Unknown
- 18. ☒ Other (Specify)
Rubber and PVC
Hose Manufactur-
ing.

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:
EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000020 JUN 11 81

JUN 11 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet See Attached Letter

gallons _____

Total Facility Area

square feet _____

acres Less than 47.47 acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☒ Known ☐ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Amerace Corporation, Swan Hose

Division Division

Street 8929 North High Street

City Worthington

State OH

Zip Code 43085

Signature [Signature]

Date 4/9/81

☒ Owner, Present

☒ Owner, Past

☐ Transporter

☐ Operator, Present

☐ Operator, Past

☐ Other

United States
Environmental Protection
Agency
Washington DC 20460

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

Name Amerace Corporation, Swan Hose Division
Street 8929 North High Street
City Worthington State Ohio Zip Code 43085

Name of Site: Stetzer Road Site

Street: Stetzer Road

Twp. Liberty County Crawford State Ohio Zip Code 44820

Name (Last, First and Title) John Keeney, Division Engineer
Phone (419) 548-6511

From (Year) 1967 To (Year) 1971

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab Hospital
17. ☐ Unknown
18. ☒ Other (Specify)
Rubber and PVC
Hose Manufactur-
ing.

[illegible]

Notification of Hazardous Waste Site

Side Two

F

Waste Quantity

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet See Attached Letter

gallons _____

Total Facility Area

square feet _____

acres Less than 47.47 acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☒ Known ☐ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Amerace Corporation, Swan HoseDivision
Street 8929 North High StreetCity Worthington State OH Zip Code 43085Signature [Signature]Date 6/9/81

- ☒ Owner, Present
☒ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other